

Washware Essentials

Kestrel Court Harbour Road Portishead Bristol BS20 7AN

Phone: 01275 400456

Web: https://www.washwareessentials.co.uk Email: enquiries@washwareessentials.co.uk

Concrete Outdoor Drinking Fountain



Product Code: GUF99-UK

Freestanding Outdoor Concrete Drinking Fountains

Product Code GUF99

- Vandal resistant concrete drinking fountain for use outside.
- Ideal for use in parks, shopping centres, schools, sea fronts and golf courses.
- Resistant to sunlight, heat, moisture, and wear.
- Stainless steel drinking fountain bowl.
- Circular brown concrete aggregate reinforced pedestal.
- Chrome plated drinking valve operated by a front mounted self closing button.
- Requires 6 x AA batteries.
- Supplied with floor anchor bolts.
- Please ensure that these are drained down and isolated in cold weather to avoid damage to the unit.
- To ensure the proper functioning and longevity of this unit, a Y-strainer must be installed as part of the water supply system. The Y-strainer is essential for protecting the internal components and maintaining the correct flow characteristics of the tap. Failure to install a Y-strainer will result in the warranty being void.

Compliant Regulations

- All water fittings are WRAS approved.
- Full approval details for your Water Board are downloadable here.

Size

- 1016mm high (to lip of fountain).
- 762mm high (Junior model).
- 356mm diameter.

Delivery

• To order 14-16 weeks.

Options

- Junior height to order in 14 to 16 weeks.
- In line water filter.

^{**}All pictures shown are for illustration purpose only and may be subject to change without notice. Actual product may vary due to product enhancement.

All dimensions shown are for guidance only and may be subject to change or alteration without notice. All items manufactured or purchased separately from a third party to fit our products should be checked against the actual dimensions of the physical product before purchase. We will not be liable for third party costs and consequential loss associated with the items not fitting third party components.**